

Oil Field Environmental Incident Summary

Incident: 20150814140217 **Date/Time of Notice:** 08/14/2015 14:02

Responsible Party: Bison Midstream, LLC

Well Operator:

Well Name: West Compressor Station

Field Name:

Well File #:

Date Incident: 8/12/2015 **Time Incident:** 01:40

Facility ID Number:

County: MOUNTRAIL

Twp: 157

Rng: 90

Sec: 6

Qtr: SE SE

Location Description: A grass fire on the north side of the West Compressor Station. The coordinates of the facility are 48.4455, -102.3526.

Submitted By: Tarik Ibrahim

Received By:

Contact Person: Tarik Ibrahim
1101 Fourth St SE, Suite 201
Stanley, ND 58784

General Land Use: Well/Facility Site

Affected Medium: Topsoil

Distance Nearest Occupied Building:

Distance Nearest Water Well:

Type of Incident: Fire

Release Contained in Dike: Yes - On Facility Site

Reported to NRC: No

Spilled Units

Recovered Units

Followup Units

Oil

Brine

Other

Description of Other Released Contaminant:

The incident resulted in liquid hydrocarbons being combusted at the flare burner.

Inspected:

Written Report Received:

Clean Up Concluded:

Risk Evaluation:

No impact to surface waters or human health.

Areal Extent:

The fire was contained on property owned by Bison Midstream, LLC.

Potential Environmental Impacts:

The fire burned approximately ¼ acre of grass on property owned by Bison Midstream, LLC.

Action Taken or Planned:

As a temporary solution, an additional pump was installed on the flare knockout vessel to remove liquids from the vessel at a higher rate. This measure has stopped liquids from reaching the flare burner. Bison Midstream, LLC is investigating the root cause of this incident and will implement a permanent corrective action as soon as possible.

Wastes Disposal Location: Bison Midstream, LLC will dispose of all waste that resulted from this incident at an authorized disposal facility.

Agencies Involved:**Updates**

Date: 8/14/2015 **Status:** Reviewed - No Action Required

Author: Suess, Bill

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Incident involved a fire. No liquids were released to the environment. No followup is necessary.